

15AU32

Third Semester B.E. Degree Examination, Aug./Sept.2020

Material Science and Metallurgy

Time: 3 hrs.

Max. Marks: 80

Note: Answer any FIVE full questions, choosing ONE full question from each module.

Module-1

- Define Atomic Packing factor. Sketch the unit cell of a HCP crystal structure. Calculate the number of atoms per unit cell. Derive an expression for the density of atomic packing [Given C = 1.633a].
 - b. With a neat sketch explain Edge and Screw dislocation.

(08 Marks)

OR

- 2 a. Draw he stress strain curves for the following material:
 - (i) Mild steel (ii) Copper (iii) Aluminium

(iv) Cast Iron.

Also explain plastic and elastic behavior of above materials.

(08 Marks)

b. Differentiate plastic deformation of single crystal by slip and twinning.

(08 Marks)

Module-2

3 a. Define Fracture. Explain Cup and Cone fracture with a neat diagram.

(08 Marks)

b. Define Creep. Explain with a neat sketch creep curve.

(08 Marks)

OR

a. Define fatigue. Explain RR Moore fatigue bending test with SN diagram. (08 Marks)
b. Explain the mechanism of fatigue. Also explain the factors which influence fatigue.

(08 Marks)

Module-3

5 a. Derive critical radius of homogeneous nucleation.

(08 Marks)

b. What is solid solution? Mention the types solid solution. Explain the factors given by Hume Rothery that govern the formation of solid solution. (08 Marks)

OR

6 a. Draw "Iron-Iron Carbide" phase diagram and show the region where the following reactions takes place: (i) Eutectic (ii) Peritectic (iii) Eutectoid.

Explain the structural changes taking place at 0.6% carbon. (10 Marks)

b. Sketch and explain the equilibrium diagram when two components A and B are completely soluble in liquid state and partially soluble in solid state. Also mention an example.

(06 Marks)

Module-4

7 a. Draw TTT diagram for 0.8% C and superimpose the cooling curves. Explain briefly.

(08 Marks)

b. With a neat sketch, explain hardening and tempering heat treatment processes. (08 Marks)

OR

		15AU32
8		t iron and (08 Marks)
9	b. With a neat sketch explain pultrusion process.	(04 Marks) (08 Marks) (04 Marks)
10	a. Write a note on properties and applications of smart materials.b. Explain working principle of optical fiber and piezo-electric materials.	(04 Marks) (08 Marks) (04 Marks)

	2 of 2	
	2 of 2	